

ANNUAL FIRE SAFETY STATISTICS

Calendar Year	2022					2021					2020				
	Fire Number	Cause Of Fire	Injuries Requiring Treatment	Deaths Related to Fire	Value of Damaged Property	Fire Number	Cause Of Fire	Injuries requiring treatment	Deaths Related to Fire	Value of Damaged Property	Fire Number	Cause Of Fire	Injuries requiring treatment	Deaths Related to Fire	Value of Damaged Property
Lynch Hall	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
O'Donoghue Hall	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
Clet Hall	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
Varsity Village	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
O'Shea Hall	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
Seton Hall	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A
Eagle Circle Apartments	1	Unintentional	0	0	\$100-999	0	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A

All Residence Hall street addresses are 5795 Lewiston Road, Lewiston, NY

Fire Safety Equipment

Each residence hall is equipped with a comprehensive fire detection and notification system. Individual rooms have smoke and heat detectors linked to a unified, building alarm system. Additionally, fire extinguishers are located throughout each residence. The NU apartments are equipped with a sprinkler system.

Residential Facility	Fire Alarms Monitored By Campus Safety	Sprinkler System	Smoke Detection	Fire Extinguisher Devices	Evacuation Plan Placards	Number of Evacuation (Fire) Drills Each Calendar Year
Lynch Hall	X		X	X	X	4
O'Donoghue Hall	X		X	X	X	4
Clet Hall	X		X	X	X	4
Varsity Village	X		X	X	X	4
O'Shea Hall	X		X	X	X	4
Seton Hall	X		X	X	X	4
Eagle Circle Apartments	X	X	X	X	X	4